

# X20 Pro Audio Decoder: USB Driver & Foobar2000 Setup Guide

**Version 2.0**

**2024-05-01**

Emoryseri c **Audio Labs**

# Chapter 1: Software Installation

## I. Computer Requirements

**Interface:** USB 2.0 or USB 3.0 port

**OS:** Windows 7 or Windows 10

**Connection:** Use the included USB cable to connect the decoder to your PC

## II. Driver Installation

**Driver File:** SXW\_setup\_WHQL\_0429A\_ASIO20230307.exe

**Pre-Install:** Power on the decoder, switch input to **USB**, and connect to the PC

**Execution:** Right-click the file and select **"Run as Administrator"**

**Pre-install:** Power on DAC, switch to USB input, connect USB cable.

**Note:** You **MUST** select "Run as Administrator" for the installer.




## III. Media Player Installation

**File:** FB\_2.1.5\_x86\_Asion\_20240908144219.exe

Follow the on-screen prompts to complete the Foobar2000 installation


## Chapter 2: Player Configuration

Run Foobar2000 and follow these steps



Step 1: Output Device Selection

1. Go to **File** -> **Preferences** [Shortcut: Ctrl+P]
2. Navigate to **Playback** -> **Output**
3. In the **Device** dropdown, select: **ASIO+DSD: SXW UAD ASIO**
4. Set **Buffer Length** to 1000ms



## Step 2: SACD &amp; DSD Settings

1. Navigate to **Tools** -> **SACD**
2. Under **Output (Per Device)**, set **Type** to **DSD**
3. Set **DSD2PCM Mode** to **Multistage (32fp)**
4. For **DSD Processor**, select **None**
5. Click **OK** to save and exit